

This is what the internals of an Induction Cooktop look like.




Westinghouse



Bosch

Insect infestation.



Coil overheating and burn out.



Insect infestation.

